98ASG ISR Infrastructure Ratings

	Mission	Mobility	Housing	Community	Installation Support
98th ASG	C2 C2 Details	C3 C3 Details	C3 C1 Details	C2 C3 Details	C3 C1 Details
235th BSB	C2 C3 Details	C2 C3 Details	C3 C1 Details	C2 C2 Details	C2 C1 Details
	_	_	_		
279th BSB	C3 C1 Details	C3 C2 Details	C4 C1 Details	C3 C2 Details	C3 C1 Details
279th BSB 280th BSB	C3 C1	C3 C2	C4 C1	C3 C2	C3 C1

98th ASG ISR Environment Ratings

	Compliance	Conservation	Restoration	Pollution Prevention	Foundation
98th ASG	C2 C2	C2 C1	C1 C1	C2 C1	C2 C2
235th BSB	C2 C1	C2 C1	C1 na	C1 C1	C2 C1
279th BSB	C2 C1	C1 C1	C1 C1	C2 C2	C1 C1
280th BSB	C1 C2	C1 C1	C1 C1	C1 C1	C1 C1
417th BSB	C2 C3	C2 C1	C1 na	C2 C1	C3 C4

98th ASG ISR Services Ratings

	Personnel & Community	Information Technology	Operations	Logistics	Engineering	Health Svcs	Command & Staff
98th ASG	C3 NA Details	C3 NA Details	NA NA Details	C2 NA Details	C3 NA Details	C3 NA Details	C2 NA Details
235th BSB	C3 NA Details	C2 NA Details	NA NA Details	C3 NA Details	C2 NA Details	C4 NA Details	C1 NA Details
279th BSB	C3 NA Details	C3 NA Details	NA NA Details	C2 NA Details	C3 NA Details	C4 NA Details	C3 NA Details
280th BSB	C3 NA Details	C3 NA Details	NA NA Details	C2 NA Details	C2 NA Details	C4 NA Details	C3 NA Details
417th BSB	C3 NA Details	C3 NA Details	NA NA Details	C1 NA Details	C2 NA Details	C3 NA Details	C2 NA Details

Summary

Component	Analysis	Corrective Action			
ISR Infrastructure	 Although many facility improvements are proceeding, the current level of SRM funding cannot keep up with normal facility aging and degradation. Deteriorated (C3) facilities significantly reduce quality of life and are a detriment to mission accomplishment. This report has been and continues to be the resource and reference document for justifying required funding. 	 Aggressively pursuing funding for various projects through execution of our Master Integrated Priority List (MIPL). Projects to improve our maintenance facilities, airfield pavements and sewer systems will be executed as funds are made available. Also a Major Construction Army (MCA) project (Record Fire range) is programmed for FY04 in Schweinfurt. 			
ISR Environment	•The environmental program throughout our communities is strong and funding is adequate for most essential services and correcting identified deficiencies. The general problem in ISR Environment is that funding is not available early enough to obligate dollars in a timely manner.	•Earlier allocations of required funds would significantly increase the ASG/BSB's ability to fund projects earlier in the FY.			
ISR Services	RecTrac in BSBs is not fully implemented. Substance abuse exceeds ISR Services standards across the BSBs due to high alcohol related incidents. IT rating (C3) is caused by lack of funds, training, and outdated equipment.	Training being provided for RecTrac to ensure full implementation by Sep 02. Awareness training on substance abuse continues to be conducted. Continue to pursue funding for IT requirements.			
SBC	•The 98 th ASG is using SBC to bench mark, identify unit cost, improve operating efficiency and review historical data.	•To continue to use SBC aggressively in seeking to stretch dollars to accomplish assigned missions.			